

FIG. 132.—Schematic drawing of Hirtz compass with legs adjusted at zero points and resting on a plane