

FIG. 135.—Reason for shift of leg of compass from zero point by the amount stated