

FIG. 152.—Schematic drawing of localizing chart, illustrating the method of obtaining measurements